

Example Harbour Services

Fictional business · example only

Example only - Workshop service visit

Fictional service report

Reference: EXAMPLE-FN-001

Date: 2026-10-13

Client: Example Willow Workshop

Site: Example training room

Address: Fictional site - no real address

Author: Example Alex Taylor

Equipment

Workshop extraction unit / Qty 1

Location: Example training bench

Serial / asset ID: EXAMPLE-001

Checklist

Exterior and mountings inspected / Checked - satisfactory

Filter condition reviewed / Needs attention

Filter nearing replacement; arrange a replacement before the next visit.

Operation observed / Checked - satisfactory

Findings & observations

EXAMPLE ONLY - Fictional observations. The unit operated during this example visit. Mountings appeared secure; the filter showed visible wear.

Recommendations & next steps

Arrange a replacement filter before the next planned visit. This example is not an inspection or compliance certification.

Visit scope

Visual observation only; internal components were not dismantled.

Review

Reviewed by Example Alex Taylor

13/10/2026, 12:58:38 UTC